



### **50° SHANK**

- Fits air drills with 50° shanks.
- Not recommended for heavy deep tillage.
- 2-1/4" (57 mm) center to center.
- 1/2" (12 mm) plow bolts.
- Can also be used on a 43° shank with the addition of a 7° wedge (100-WDG-0700). See page 89 for more details.



200-QCA-5020

### **50° SHANK**

- Fits European built tillage and seeding implements.
- 63 mm to 80 mm center to center.
- M12-DIN608 10.9 plow bolts.



200-QCA-5030

### **50° SHANK**

- Fits Horsch shanks.
- 57 mm center to center.
- M12-DIN608 10.9 plow bolts.

## Don't forget the Speed Release Tool

#### 200-REL-1010

The speed-release tool must be used to remove 200 and 410 Series sweeps and openers off the Speed-Loc<sup>TM</sup> adapters.

# Not sure which adapter is for you or which bolts you need?

Refer to our *Speed-Loc*<sup>TM</sup> adapter chart on pages 72-73.

For a complete list of bolt lengths, see pages 91.